



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	308	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2201		Rogene	DR

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		

**Comments:** Unknown MH# u/s of MH 00692785

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 5

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0005.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 308

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\308.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	308	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	
<b>House Number</b>	2200	<b>Street Prefix:</b>		<b>Street Name:</b>	
				Kelly	AVE
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		
<b>Comments:</b>	MH 00691115				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 6

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0006.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 308

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\308.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	308	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
2201		Rogene	DR		
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	500		
<b>Comments:</b>	MH 00691116				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0007.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 308

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\308.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	308	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WRR02
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	4	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
2201		Rogene	DR

<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	11=Field	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		

**Comments:** MH 00691117

## SMOKE TEST PHOTOS



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0008.JPG

**Image Status:** Image found and displayed.



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 308

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\308.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	309	<b>Date:</b>	10/18/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	5	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**








**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

<b>M&amp;E</b> Metcalf & Eddy			
Project: WRPA	Sewershed: Jones Falls	Date/Time: 10.26.04 11:35am	
Unique ID: 309	Location: Park Heights		
Set-up : # 5			
Crew: Transviron			
Sketch: Not to scale			
			
<b>LEGEND</b>			
	RESIDENTIAL UNIT (SMOKE)	 SEWER PIPELINE	 STORM INLET
	RESIDENTIAL UNIT (NO SMOKE)	 DEFECTS	 BLOWER

Sketch No: 309

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\309.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

Unique Test ID	309	Date:	10/18/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	5	Priority CCTV:	

---

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

---

## SMOKE TEST PHOTOS

Photo No:  
Filename Path:  
  
Image Status: No image name specified.

Photo No:  
Filename Path:  
  
Image Status: No image name specified.








Photo No:  
Filename Path:  
  
Image Status: No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH

<b>M&amp;E</b> Metcalf & Eddy			
Project: WRPA	Sewershed: Jones Falls	Date/Time: 10.26.04 11:35am	
Unique ID: 309	Location: Park Heights		
Set-up : # 5			
Crew: Transviron			
Sketch: Not to scale			
			
<b>LEGEND</b>			
	RESIDENTIAL UNIT (SMOKE)	 SEWER PIPELINE	 STORM INLET
	RESIDENTIAL UNIT (NO SMOKE)	 DEFECTS	 BLOWER

Sketch No: 309

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\309.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	310	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 310

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\310.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	310	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
3904		Fordleigh	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	4=Major
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**  
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**  
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 310

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\310.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	310	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	2	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
3917		Fordleigh	ROAD

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 3

**Filename Path:**  
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0003.JPG

**Image Status:** Image found and displayed.



**Photo No:** 4

**Filename Path:**  
X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_B\B\_2004\_1026Image0004.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 310

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\310.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6201		Biltmore	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0007.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	6203	<b>Street Prefix:</b>		<b>Street Name:</b>	Biltmore	<b>Street Type:</b>	AVE
<b>Source Type:</b>	05= Downspout	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>	3=Moderate		
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	700				
<b>Comments:</b>							

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0009.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	3	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6203		Biltmore	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	9=Yard-Side	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	700		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0010.JPG

**Image Status:** Image found and displayed.



**Photo No:** 22

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID311-A3\_2005\_0523Image022.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	4	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6204		Park Heights	AVE

<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0011.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	5	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6204		Park Heights	AVE		
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	0		
<b>Comments:</b>					

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0012.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	6	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6207		Biltmore	AVE

<b>Source Type:</b>	02= Service Line	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	100		

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID311-A6\2005\_0523Image023.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	311	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR27
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	7	<b>Setup No:</b>	3	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6204		Park Heights	AVE		
<b>Source Type:</b>	12= MH Frame Seal	<b>Location:</b>	8=Yard-Back	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	0		
<b>Comments:</b>	unmapped MH				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0014.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

Unique Test ID	311	Date:	10/26/2004	MeterBasin:	
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	0	Setup No:	3	Priority CCTV:	

---

House Number	Street Prefix:	Street Name:	Street Type:
--------------	----------------	--------------	--------------

Source Type:	Location:	Severity:
Sector:	Drainage Area: 0	
Comments:	No defects observed	

---

## SMOKE TEST PHOTOS

Photo No:  
Filename Path:  
  
Image Status: No image name specified.

Photo No:  
Filename Path:  
  
Image Status: No image name specified.


Photo No:  
Filename Path:  
  
Image Status: No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 311

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\311.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	312	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR05
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	1	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
6100		Cross Country	Blvd

<b>Source Type:</b>	01= Main Sewer	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	1=Public	<b>Drainage Area:</b>	500		

**Comments:** elementary school / ground

## SMOKE TEST PHOTOS



**Photo No:** 1

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\UTID312-A1\_2005\_0517Image001.JPG

**Image Status:** Image found and displayed.



**Photo No:** 2

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Retakes\UTID312-A1\_2005\_0517Image002.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 312

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\312.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

<b>Unique Test ID</b>	312	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	01_WR05
<b>Observer ID:</b>	A	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	2	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>		
6100		Cross Country	Blvd		
<b>Source Type:</b>	04= Cleanout	<b>Location:</b>	7=Yard-Front	<b>Severity:</b>	3=Moderate
<b>Sector:</b>	2=Private	<b>Drainage Area:</b>	150		
<b>Comments:</b>	elementary School / ground				

## SMOKE TEST PHOTOS



**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:** 3

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\1026-2004\T-1\PLAYER\_A\A\_2004\_1026Image0003.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 312

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\312.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

---

<b>Unique Test ID</b>	312	<b>Date:</b>	10/26/2004	<b>MeterBasin:</b>	
<b>Observer ID:</b>	B	<b>Crew:</b>	T-1	<b>Dye Test Recommended:</b>	N
<b>Defect No:</b>	0	<b>Setup No:</b>	1	<b>Priority CCTV:</b>	

---

<b>House Number</b>	<b>Street Prefix:</b>	<b>Street Name:</b>	<b>Street Type:</b>
---------------------	-----------------------	---------------------	---------------------

<b>Source Type:</b>	<b>Location:</b>	<b>Severity:</b>
<b>Sector:</b>	<b>Drainage Area:</b> 0	
<b>Comments:</b> No defects observed		

---

## SMOKE TEST PHOTOS

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.

**Photo No:**

**Filename Path:**

**Image Status:** No image name specified.






# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 312

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\312.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.